
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 7/22/2009
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp □ Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S02AA1030MH	Test ID: <u>D1032-027023</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S04AA1012MH
120.9000015	10		Tap Factory	From 5011 Gwynn Oak
120.9000015			Dye Test Visible	@ TF - downspout
120.9000015			Manhole	S02AA1030MH
120.9000015			End of Survey	DYE TEST COMPLETED